



APPENDIX B


MAPS OF GEOMORPHIC FEATURES AND PRESSURES RECORDED DURING FIELD SURVEYS

















River Nith restoration, cbec UK Ltd, October 2013